



Clause 36 state diagram

Adam Healey
IEEE P802.3az Task Force Meeting
Geneva, Switzerland
May 2010



Proposed changes

- Change the state diagram as shown on the next slide
- Delete rx_ts_timer definition from 36.2.5.1.7
- Remove T_{SR} row from Table 36-3b

