

IEEE P802.3bv D2.3 GEPOF 3rd Working Group recirculation ballot comments

Cl 114 SC 114.8.1 P111 L19 # 1

Kobayashi, Shigeru

TE Connectivity

Comment Type **E** Comment Status **X**

The cutting tool and/or using the cutting tool practically cannot be controlled.

SuggestedRemedy

It would be appropriate to use "should" rather than "shall".

Proposed Response Response Status **O**

Cl 114 SC 114.7 P107 L # 2

Kobayashi, Shigeru

TE Connectivity

Comment Type **E** Comment Status **X**

The vertical axis of Figure 114-37, -38, and -39 is not "transfer function lower bound".

SuggestedRemedy

It should be "Transfer function magnitude" followed by the tables 114-13, -14, and -15.

Proposed Response Response Status **O**