

Approved Responses

IEEE P802.3cf D3.1 YANG Data Model Definitions 1st Sponsor recirculation ballot comments

Cl 4 SC 4 P19 L6 # r01-11
 Remein, Duane Huawei Technologies
Comment Type E Comment Status A bucket
 Abbreviations should be in alphabetical order
SuggestedRemedy
 reorder
Response Response Status C
 ACCEPT.

Cl 5 SC 5.3.2 P27 L3 # r01-12
 Remein, Duane Huawei Technologies
Comment Type E Comment Status A bucket
 "text of description" missing article. Same error pg/line: 56/3, 81/3, and 133/3
SuggestedRemedy
 change to "text of the description" in 4x
Response Response Status C
 ACCEPT.

Cl 5 SC 5.2 P21 L34 # r01-1
 Anslow, Peter Ciena Corporation
Comment Type E Comment Status A bucket
 As noted in comment #202 against P802.3cf D2.2, When tables split across pages, the bottom ruling of the table on all but the last page should be "very thin" and the final bottom ruling should follow the table format as "Thin". This is not done correctly in D3.1 for:
 Table 5-1 where the bottom ruling on page 21 is not overridden to be "Very Thin" (indicating that the table continues)
 Table 6-1 where the bottom ruling on page 53 is ok, but the bottom ruling on page 54 should be "Thin" to indicate the end of the table.
 Table 7-1 where the bottom rulings on page 75 and on page 76 are not overridden to be "Very Thin" (indicating that the table continues)
 Table 8-1 where the bottom rulings on page 127 and on page 128 are not overridden to be "Very Thin" (indicating that the table continues)
SuggestedRemedy
 In Table 5-1 override the bottom ruling on page 21 to be "Very Thin" while leaving the bottom ruling on page 22 "Thin".
 In Table 6-1 make the bottom ruling on page 54 "Thin" while leaving the bottom ruling on page 53 "Very Thin".
 In Table 7-1 override the bottom rulings on page 75 and page 76 to be "Very Thin" while leaving the bottom ruling on page 77 "Thin".
 In Table 8-1 override the bottom rulings on page 127 and page 128 to be "Very Thin" while leaving the bottom ruling on page 129 "Thin".
Response Response Status C
 ACCEPT.

Cl 5 SC 5.3.2.1 P27 L21 # r01-13
 Remein, Duane Huawei Technologies
Comment Type T Comment Status A
 The statement "revision <publication-date-in-yyyy-mm-dd-format> {" should be properly indented. Same issues pg/line: 44/44, 56/17, 81/18, and 133/18
SuggestedRemedy
 Add indenting 5x
Response Response Status C
 ACCEPT.

Cl 5 SC 5.3.2.2 P45 L5 # r01-2
 Zhuang, Yan Huawei Technologies
Comment Type G Comment Status A
 we've changed the reference of iana-if-type in ethernet-interface module and should change it in other modules as well.
SuggestedRemedy
 Delete editorial notes and change the reference of iana-if-type to "http://www.iana.org/assignments/yang-parameters/iana-if-type@2018-07-03.yang"
Response Response Status C
 ACCEPT.

Approved Responses

IEEE P802.3cf D3.1 YANG Data Model Definitions 1st Sponsor recirculation ballot comments

Cl 7 **SC 7.4.2** **P80** **L26** # **r01-14**
 Remein, Duane Huawei Technologies
Comment Type **T** **Comment Status** **A**
 Incomplete sentence in description:
 "For a complete description of how the LLID is used in an EPON device.;"
SuggestedRemedy
 Change to: "For a complete description of how the LLID is used in an EPON device see Std 802.3, Clause 65 for 1G-EPON and Clause 76 for 10G-EPON.;"
Response **Response Status** **C**
 ACCEPT IN PRINCIPLE.

 Comment is against page 82, line 26.

 "For a complete description of how the LLID is used in an EPON device see IEEE Std 802.3, Clause 65 for 1G-EPON and Clause 76 for 10G-EPON.;"

Cl 7 **SC 7.4.2** **P82** **L10** # **r01-15**
 Remein, Duane Huawei Technologies
Comment Type **E** **Comment Status** **A** *bucket*
 There are two instances where we changed
 "This object indicates that the given Ethernet interface supports MPCP ..." to
 "This object indicates that the given EPON interface supports MPCP ..."
 I don't know of any EPON interfaces which don't support MPCP.
SuggestedRemedy
 At the following locations change:
 "This object indicates that the given EPON interface supports MPCP ... " to :
 "This object indicates that the given interface supports MPCP ... "
 Pg/Line - 81/10, 90/52
Response **Response Status** **C**
 ACCEPT.

Cl 7 **SC 7.4.2** **P87** **L42** # **r01-4**
 Zhuang, Yan Huawei Technologies
Comment Type **E** **Comment Status** **A** *bucket*
 missing period.
SuggestedRemedy
 change:
 description
 "Exit EPON logical interface power-down state";
 to
 description
 "Exit EPON logical interface power-down state";
Response **Response Status** **C**
 ACCEPT.

Cl 7 **SC 7.4.2** **P90** **L62** # **r01-16**
 Remein, Duane Huawei Technologies
Comment Type **E** **Comment Status** **A** *bucket*
 There are five instances where we changed
 "an Ethernet interface implementing MPCP, ..." to
 "an EPON interface implementing MPCP"
 I don't know of any EPON interfaces which don't support MPCP.
SuggestedRemedy
 At the following locations change:
 " an EPON interface implementing MPCP, ..." to
 "an EPON interface, ..."
 Pg/Line - 90/62, 97/41, 102/62, 104/37, & 108/30
Response **Response Status** **C**
 ACCEPT.

Approved Responses

IEEE P802.3cf D3.1 YANG Data Model Definitions 1st Sponsor recirculation ballot comments

Cl 7 SC 7.4.2 P94 L34 # r01-5
 Zhuang, Yan Huawei Technologies
 Comment Type E Comment Status A bucket
 both "the" and "a" appear as article and delete one.
 same at:
 pg 94, line 30 and line 61.
 SuggestedRemedy
 change
 This object is applicable for an OLT and has the a distinct value for each logical link.
 to
 This object is applicable for an OLT and has a distinct value for each logical link.
 Response Response Status C
 ACCEPT.

Cl 7 SC 7.4.2 P108 L48 # r01-17
 Remein, Duane Huawei Technologies
 Comment Type ER Comment Status A
 phrase has unmatched single quotes - "... 'Carrier Extend Error' ..."
 SuggestedRemedy
 Change to "... 'Carrier Extend Error' ..." (matched single quotes)
 Response Response Status C
 ACCEPT.

Cl 7 SC 7.4.2 P108 L48 # r01-6
 Zhuang, Yan Huawei Technologies
 Comment Type E Comment Status A bucket
 'Carrier Extend Error' has error character
 SuggestedRemedy
 change
 'Carrier Extend Error'
 to
 'Carrier Extend Error'
 Response Response Status C
 ACCEPT.

Cl 7 SC 7.4.2 P109 L39 # r01-18
 Remein, Duane Huawei Technologies
 Comment Type E Comment Status A bucket
 Unconstrained "it" in phrase "it is a count". Same unconstrained it on pg 110 line 4.
 SuggestedRemedy
 Change "it is a count of" to "this object represents a count of" 2x
 Response Response Status C
 ACCEPT.

Cl 7 SC 7.4.2 P116 L35 # r01-19
 Remein, Duane Huawei Technologies
 Comment Type T Comment Status A
 This statement is self contradiction: "A count of the number of times a frame reception event results in a frame being queued in (for ONUs) or received from (for OLTs) the corresponding queue. This object is incremented by one for each frame received, when it is input into the associated queue." The last sentence does not agree with the first, in the OLT the received frame is not "put into the associated queue".
 SuggestedRemedy
 Change
 "This object is incremented by one for each frame received, when it is input into the associated queue." to read
 "This object is incremented by one for each frame written to (in the case of the ONU) or received for (in case of the OLT) the associated queue."
 Response Response Status C
 ACCEPT.

Cl 7 SC 7.4.2 P116 L45 # r01-20
 Remein, Duane Huawei Technologies
 Comment Type TR Comment Status A
 This sentence applies only to the OLT "It has a distinct value for each logical link and each queue."
 SuggestedRemedy
 Change to "At the OLT, it has a distinct value for each logical link and each queue."
 Response Response Status C
 ACCEPT.

Cl 7 SC 7.4.2 P121 L19 # r01-7
 Zhuang, Yan Huawei Technologies

Comment Type **G** *Comment Status* **A**
 yang error reported by yang validation tools.

SuggestedRemedy
 change
 leaf mpcp-round-trip-time {
 when "../ompe-mode = 'olt'";
 to
 leaf mpcp-round-trip-time {
 when "../ompe-mode = 'olt'";

Response *Response Status* **C**
 ACCEPT.

Cl 7 SC 7.4.2 P121 L45 # r01-8
 Zhuang, Yan Huawei Technologies

Comment Type **G** *Comment Status* **A**
 yang error reported by yang validation tools

SuggestedRemedy
 change
 leaf mpcp-maximum-grant-count {
 when "../ompe-mode = 'onu'";
 to
 leaf mpcp-maximum-grant-count {
 when "../ompe-mode = 'onu'";

Response *Response Status* **C**
 ACCEPT.

Cl 7 SC 7.4.2 P122 L26 # r01-9
 Zhuang, Yan Huawei Technologies

Comment Type **G** *Comment Status* **A**
 yang errors reported by yang validation tools

SuggestedRemedy
 change
 leaf mpcp-maximum-queue-count-per-report {
 when "../ompe-mode = olt";
 to
 leaf mpcp-maximum-queue-count-per-report {
 when "../ompe-mode = olt";

Response *Response Status* **C**
 ACCEPT.

Cl 8 SC 8.5.2 P133 L40 # r01-3
 Zhuang, Yan Huawei Technologies

Comment Type **G** *Comment Status* **A**
 we've changed the reference of iana-if-type in ethernet-interface module and should change it in other modules as well

SuggestedRemedy
 Delete the editor note in line 39-40.
 Change the reference of iana-if-type to "http://www.iana.org/assignments/yang-parameters/iana-if-type@2018-07-03.yang"

Response *Response Status* **C**
 ACCEPT.

Cl 8 SC 8.5.2 P138 L65 # r01-10
 Zhuang, Yan Huawei Technologies

Comment Type **G** *Comment Status* **A**
 string type is not defined in 'yang'.

SuggestedRemedy
 change
 typedef vendor-oui {
 type yang:string {
 to
 typedef vendor-oui {
 type string {

Response *Response Status* **C**
 ACCEPT.