

IEEE P802.3 Maintenance

Pat Thaler for David Law

July 8th, 2002

Vancouver, BC

Maintenance Requests Status

- 100 Maintenance requests
- 6 new Maintenance requests since March
- Opening meeting status -

Awaiting ballot	11
Awaiting clarification	7
Errata	2
To be categorised	4
Review by Technical experts	3
Withdrawn	3
Published	70

IEEE P802.3aj Maintenance #7

- IEEE P802.3ag PAR approved by NesCom
 - Approved 13th June 2002.
- Expect to ballot out of November plenary
 - Awaiting input from IEEE Std-802.3ae editing
 - Some comments submitted to the IEEE Editor may require balloting and will be submitted as Revision Requests

Results of the week

- Maintenance committee meeting this week
 - Reviewed status of existing revision requests
 - Classified new revision requests
 - 3 moved to ballot (1088, 1090, 1096)
 - 2 editorial errata (1064, 1089)
 - 1 Rejected (1072)
 - 1 Withdrawn (1057)
 - 1051 –a completed revision was also reviewed
 - 3 remain incomplete awaiting response from requesters
 - 2 await other events for review
- Circulate ballot pre-view draft for November plenary
 - May include changes from 802.3ae comment resolution

1051

- Changed dot3adAgg...Priority object syntax in Annex 30C (SNMP)
 - From Integer (0..255)
 - To Integer (0..65535)
 - Balloted, approved and published in 2002
- Ideally should have deprecated objects and added new correct ones.
- Since change is published, further action could cause problems – maintenance will not initiate action.

Editorial

- 1064 – incorrect subclause number in internal reference.
- 1089 – editorial corrections to Pause Operation Receive state diagram
 - Applying parenthesis to equations for clarity
 - Adding “data” definition
 - Correct grammar typo.

Maintenance Motion

- Affirm that 1064 and 1089 are editorial and may be applied to 802.3 as errata.
 - Y_71_
 - N_0_
 - A_4_
 - Moved by maintenance.

Maintenance Web Information

- The Maintenance web site is at:

<http://www.ieee802.org/3/maint/index.html>

- The Maintenance request form is available at:

http://www.ieee802.org/3/private/maint/revision_request.html

Username: ****

Password: ****

Password is case sensitive

Rejected item: 1072

- Requested allocation of a Next Page Message Code Field to a company
 - Code space is 0..2047 – too small to allow proprietary assignments
 - Would require a PAR to amend the standard to provide a code space increase
 - Therefore, not appropriate for maintenance.