

+-----+
| 8802-3/802.3 REVISION REQUEST 1089 |
+-----+

DATE: 7th Dec, 2001
NAME: Shimon Muller
COMPANY/AFFILIATION: Sun Microsystems Inc.
E-MAIL: shimon.muller@sun.com

REQUESTED REVISION:
STANDARD: IEEE Standard 802.3, 2000 Edition
CLAUSE NUMBER: Annex 31B
CLAUSE TITLE: MAC Control Pause Operation

PROPOSED REVISION TEXT:

See IEEE P802.3aj draft.

RATIONALE FOR REVISION:

1. The exit conditions from state WAIT FOR TRANSMISSION COMPLETION in Figure 31B-2 is missing parentheses so can be interpreted incorrectly.
2. The state diagram in Figure 31B-2 uses the variable "data" that has not been defined anywhere.
3. There is a typo in subclause 31B.3.6.3.

IMPACT ON EXISTING NETWORKS:

+-----+
| Please attach supporting material, if any |
| Submit to:- Bob Grow, Chair IEEE 802.3 |
| E-Mail: Bob.Grow@intel.com |
| |
| +----- For official 802.3 use -----+ |
| REV REQ NUMBER: 1089 |
| DATE RECEIVED: 7th Dec, 2001 |
| ~~EDITORIAL/TECHNICAL~~ |
| ACCEPTED/~~DENIED~~ |
| BALLOT REQ'D YES/~~NO~~ |
| COMMENTS: 26-Sep-03 Ver: D2.1 Status: P |
+-----+

+-----+
| For information about this Revision Request see - |
| http://www.ieee802.org/3/maint/requests/revision_history.html#REQ1089 |
+-----+