

-----+  
| 8802-3/802.3 REVISION REQUEST 1240 |  
+-----+

DATE: 3rd Mar, 2013  
NAME: David Law  
COMPANY/AFFILIATION: Hewlett-Packard Ltd  
E-MAIL: dlaw@hp.com

REQUESTED REVISION:  
STANDARD: IEEE Std 802.3-2012  
CLAUSE NUMBER: Table 30-5  
CLAUSE TITLE: EFM Capabilities

PROPOSED REVISION TEXT:

- [1] Delete the table entry for aMACControlFunctionsSupported.
- [2] Change 'oOAM ... class (30.3.3)' to read 'oOAM ... class (30.3.6)'.

RATIONALE FOR REVISION:

There is a duplicate entry for aMACControlFunctionsSupported in Table 30-5 'EFM capabilities' in the oOAM managed object class in IEEE Std 802.3-2012 (also in IEEE Std 802.3-2008). This is a duplicate of the correct entry for aMACControlFunctionsSupported in Table 30-1b 'Capabilities' in the oMACControlEntity managed object class. MAC Control Functions are part of MAC Control, not EFM OAM.

In addition the cross-reference provided for the 'oOAM managed object class' to subclause 30.3.3 'MAC control entity object class' is incorrect; it should be to subclause 30.3.6 'OAM object class'.

IMPACT ON EXISTING NETWORKS:

None.

-----+  
| Please attach supporting material, if any |  
| Submit to:- David Law, Chair IEEE 802.3 |  
| and copy:- Wael William Diab, Vice-Chair IEEE 802.3 |  
| At:- E-Mail: stds-802-3-maint-req@ieee.org |  
| |  
| +----- For official 802.3 use -----+ |  
REV REQ NUMBER: 1240		
DATE RECEIVED: 3rd Mar, 2013		
EDITORIAL/TECHNICAL		
ACCEPTED/DENIED		
BALLOT REQ'D YES/NO		
COMMENTS: XX-Xxx-XX Ver: D1.0 Status: R		
+-----+

For information about this Revision Request see -  
[http://www.ieee802.org/3/maint/requests/revision\\_history.html#REQ1240](http://www.ieee802.org/3/maint/requests/revision_history.html#REQ1240)