

+-----+
| IEEE 802.1 REVISION REQUEST 0079 |
+-----+

DATE: 31 October 2012
NAME: Paul Woods
COMPANY/AFFILIATION: Aptina, LLC
E-MAIL: pwoods@aptina.com<<mailto:pwoods@aptina.com>> (via Dave Olsen
dolsen@harman.com<<mailto:dolsen@harman.com>>)

REQUESTED REVISION:
STANDARD: 802.1AS-2011
CLAUSE NUMBER: 11.2.16.1
CLAUSE TITLE:

RATIONALE FOR REVISION:

Figure 11-8: In MDPdelayReq state machine, state RESET, it seems to need to clear rcvdPdelayResp because otherwise the check performed in state WAITING_FOR_PDELAY_RESP could occur repeatedly on the old (bad) message.

PROPOSED REVISION TEXT:

See Above

IMPACT ON EXISTING NETWORKS:

None. Changes could help implementers avoid confusion.

+-----+
| Please attach supporting material, if any |
| Submit to:- Tony Jeffree, Chair IEEE 802.1 |
| and copy:- Glenn Parsons, Vice-Chair IEEE 802.1 |
| E-Mail: stds-802-1-maint-req@ieee.org |
| |
| +----- For official 802.1 use -----+ |
	REV REQ NUMBER: 0079	
	DATE RECEIVED: 11/01/2012	
	EDITORIAL/TECHNICAL	
	ACCEPTED/DENIED	
	BALLOT REQ'D YES/NO	
	Status: R	
	+-----+	
+-----+