
| IEEE 802.1 REVISION REQUEST 0092 |

DATE: 27 December, 2012
NAME: Sung Hyuk Byun
COMPANY/AFFILIATION: ETRI
E-MAIL: shbyun@etri.re.kr
REQUESTED REVISION:
STANDARD: 802.1Qbg-2012
CLAUSE NUMBER: 41.5.2
CLAUSE TITLE: Bridge VDP state machine

RATIONALE FOR REVISION:

In Figure 41-8 Bridge VDP state machine, WAIT_STATION_CMD state include following equation :

vsi State = operCmd.Mode1;

But, there is no definition of operCmd.Mode1 in the standard.
operCmd.Mode1 should be a mistyping of operCmd.TLVtype.

PROPOSED REVISION TEXT:

Change the following equation at WAIT_STATION_CMD state of Figure 41.8, Clause 41.5.2

vsi State = operCmd.Mode1

with

vsi State = operCmd.TLVtype

IMPACT ON EXISTING NETWORKS:

There is no impact on existing networks.

Please attach supporting material, if any
Submit to: - Tony Jeffree, Chair IEEE 802.1
and copy: - Glenn Parsons, Vice-Chair IEEE 802.1
E-Mail: stds-802-1-maint-req@ieee.org

----- For official 802.1 use -----
REV REQ NUMBER: 0092
DATE RECEIVED: 01/09/2013
EDITORIAL/TECHNICAL
ACCEPTED/DENIED
BALLOT REQ'D YES/NO
Status: R
