

+-----+  
| IEEE 802.1 REVISION REQUEST 0107  
+-----+

DATE: January 29, 2013  
NAME: Paul Bottorff  
COMPANY/AFFILIATION: Hewlett-Packard  
E-MAIL: paul.bottorff@hp.com

REQUESTED REVISION:  
STANDARD: 802.1qbg  
CLAUSE NUMBER: 12, 17  
CLAUSE TITLE: Management protocol

RATIONALE FOR REVISION:

Clause 12 specifies object called evbSysEcpDfltAckTimerInit and evbSysEcpDfltMaxTries. however clause 17 references objects by the names ieee8021BridgeEvbSysEcpAckTimer and ieee8021BridgeEvbSysEcpMaxTries in table 17-26 and ieee8021BridgeEvbSysEcpMaxRetries in the MIB text. These names should be alligned and MaxTries should be relaced with MaxRetries.

PROPOSED REVISION TEXT:

Replace evbSysEcpDfltMaxTries in clause 12 and table 12-17 with evbSysEcpDfltMaxRetries.

Replace ieee8021BridgeEvbSysEcpAckTimer and ieee8021BridgeEvbSysEcpMaxTries in table 17-26 with ieee8021BridgeEvbSysEcpDfltAckTimerInit and ieee8021BridgeEvbSysEcpDfltMaxRetries.

Deprecate ieee8021BridgeEvbSysEcpAckTimer and ieee8021BridgeEvbSysEcpMaxRetries from the SNMP MIB and add new replacement objects called ieee8021BridgeEvbSysEcpDfltAckTimerInit and ieee8021BridgeEvbSysEcpDfltMaxRetries.

IMPACT ON EXISTING NETWORKS:

<replace this text with a description of impact on existing networks>

+-----+  
| Please attach supporting material, if any  
| Submit to:- Tony Jeffree, Chair IEEE 802.1  
| and copy:- Glenn Parsons, Vice-Chair IEEE 802.1  
| E-Mail: stds-802-1-maint-req@ieee.org  
|  
| +----- For official 802.1 use -----+  
| REV REQ NUMBER: 0107  
| DATE RECEIVED: March 19 2013  
| EDITORIAL/TECHNICAL  
| ACCEPTED/DENIED  
| BALLOT REQ'D YES/NO  
| Status: R  
+-----+