

## IEEE 802.17 Maintenance Request 0023

MR number 0023 Classification Technical Date received 3/13/2005 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 112 Subclause 7.5.7.2.4 Figure \_\_\_\_\_ Table 7.11

Surname Lemon Given Name John

**Perceived Problem** [ If more space is needed, please provide an additional file, preferably as plain text. ]

Table 7.11, Table 7.12, and Table 7.13 direct taking the Min() of 0 and the credit value after being decremented for one byte.

**Proposed Remedy** [ If more space is needed, please provide an additional file, preferably as plain text. ]

In Table 7.11 Row 1, Table 7.12 Row 1, Table 7.13 Row 1, and Table 7.13 Row 2, change "Min" to "Max". Move the definition of Max forward to Clause 7.

**Rationale For Remedy** [ If more space is needed, please provide an additional file, preferably as plain text. ]

The current text would always drop the credits to zero or to negative credits for every byte transmitted. This check is supposed to be preventing the credits from dropping below zero.

**Remedy's Effect On Existing Equipment** [ If more space is needed, provide an additional file, preferably as plain text. ]

None.

**When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.**