

IEEE 802.17 Maintenance Request 0055

MR number 0055 Classification Technical Date received 3/16/2005 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 139 Subclause 7.6.3.8.4 Figure _____ Table 7.22

Surname Lemon Given Name John

Perceived Problem [If more space is needed, please provide an additional file, preferably as plain text.]

Multicast or broadcast control frames can increment the ttlExpiredFrames counter.

Proposed Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

Add "frame.ft == FT_DATA" to the condition for Table 7.22 Row 15.

Rationale For Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

TTL expiration was not supposed to be applied to control frames.

Remedy's Effect On Existing Equipment [If more space is needed, provide an additional file, preferably as plain text.]

None.

When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.