

## IEEE 802.17 Maintenance Request 0088

MR number 0088 Classification Technical Date received 10/18/2005 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 278 Subclause 10.4.10.6 Figure \_\_\_\_\_ Table 10.15

Surname Sood Given Name Mohit

**Perceived Problem** [ If more space is needed, please provide an additional file, preferably as plain text. ]

Line 13 : dsWrapPoint = totalHopsTx[otherRi], Line 15 and 16 : wrapPoint = totalHopsRx[otherRi] do not give the desired wrap points in the respective scenarios.

**Proposed Remedy** [ If more space is needed, please provide an additional file, preferably as plain text. ]

Line 13 : dsWrapPoint = totalHopsTx[myRi], Line 15 and 16 : wrapPoint = totalHopsRx[myRi]

**Rationale For Remedy** [ If more space is needed, please provide an additional file, preferably as plain text. ]

Line 13 : totalHopsTx[otherRi] gives hops to upstream wrap point instead of hops to downstream wrap point. Line 15 & 16 : totalHopsRx[otherRi] gives hops to downstream wrap point instead of hops to upstream wrap point.

**Remedy's Effect On Existing Equipment** [ If more space is needed, provide an additional file, preferably as plain text. ]

The Head station would be able to calculate correct values of IrttToTail and FRTT.

**When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.**