

IEEE 802.17 Maintenance Request 0099

MR number 0099 Classification Technical Date received 2/22/2006 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 264 Subclause 10.4.5.4 Figure _____ Table 10.10

Surname Bruckman Given Name Leon

Perceived Problem [If more space is needed, please provide an additional file, preferably as plain text.]

Wrong description od row 10.10-4. The station becomes a "head" not a tail.

Proposed Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

In the decription of Row 10.10-4 replace : "..and it is the tail of the.." with: "..and it is the head of the..."

Rationale For Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

Consistency

Remedy's Effect On Existing Equipment [If more space is needed, provide an additional file, preferably as plain text.]

No effect

When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.