

## IEEE 802.17 Maintenance Request 0103

MR number 0103 Classification Technical Date received 6/19/2006 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 334 Subclause 11.6.4.4 Figure \_\_\_\_\_ Table 11.14

Surname Lemon Given Name John

**Perceived Problem** [ If more space is needed, please provide an additional file, preferably as plain text. ]

The action of Row 17 does not result in the checksum value being stored for later use.

**Proposed Remedy** [ If more space is needed, please provide an additional file, preferably as plain text. ]

Change the action of Row 17 to:  
myTopoInfo.myChecksum.value = ComputeTc()

**Rationale For Remedy** [ If more space is needed, please provide an additional file, preferably as plain text. ]

ComputeTc() returns the checksum value, so the returned value needs to be obtained from the function result, and it needs to be stored in the standard location used elsewhere.

**Remedy's Effect On Existing Equipment** [ If more space is needed, provide an additional file, preferably as plain text. ]

None.

**When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.**