

IEEE 802.17 Maintenance Request 0109

MR number 0109 Classification Technical Date received 6/19/2006 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 311 Subclause 11.4.3.4 Figure _____ Table _____

Surname Lemon Given Name John

Perceived Problem [If more space is needed, please provide an additional file, preferably as plain text.]

Reference is given to the wrong subclause, and no reference is given to the variable from which this obtains its value.

Proposed Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

Change
"multiChokeIndOption defined in 10.2.2."
to
"myTopoInfo.multichokeUser defined in 11.2.5."

Rationale For Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

This corrects the reference, specifies the correct variable, and makes this subclause consistent with its neighboring subclauses.

Remedy's Effect On Existing Equipment [If more space is needed, provide an additional file, preferably as plain text.]

None.

When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.