

IEEE 802.17 Maintenance Request 0126

MR number 0126 Classification Technical Date received 9/15/2006 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 351 Subclause 1.6.6.5 Figure _____ Table 11.16

Surname Juźwiak Given Name Piotr

Perceived Problem [If more space is needed, please provide an additional file, preferably as plain text.]

If topoEntryInvalidDefect is set in TopologyValidation state machine It isn't cleared when topology is valid.

Proposed Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

Add line:
topoEntryInvalidDefect = FALSE;

to actions of row 9 in table 11.16.

Rationale For Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

If there is no defect and topology is valid, topology defect shouldn't be announced.

Remedy's Effect On Existing Equipment [If more space is needed, provide an additional file, preferably as plain text.]

None.

When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.