

IEEE 802.17 Maintenance Request 0133

MR number 0133 Classification Technical Date received 7/10/2008 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 162 Subclause 7.7.1.6.4 Figure _____ Table 7.29

Surname Lemon Given Name John

Perceived Problem [If more space is needed, please provide an additional file, preferably as plain text.]

Control frame fields are being treated as data frames.

Proposed Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

From Row 5, delete the following assignments from the action column:

```
frame.ef = 0;  
frame.fi = FI_NONE;  
frame.so = 0;
```

Rationale For Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

Control frames do not have an extendedControl field, and therefore do not have these subfields.

Remedy's Effect On Existing Equipment [If more space is needed, provide an additional file, preferably as plain text.]

None, because no one could have created equipment that filled in fields that don't exist.

When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.