

IEEE P802.3dd D3.0 Clause 104 Maintenance Initial Sponsor ballot comments

Cl 0 SC 0 P18 L 44 # I-4

Maytum, Michael None-Retired

Comment Type **TR** Comment Status **R** Editorial

text states "exceed Vpup as defined in Table 104-12"

SuggestedRemedy

No Vpup value in Table 104-12, instert Vpup value

Response Response Status **W**

REJECT.

The CRG disagrees with the commenter.

The Vpup value is item 1 in Table 104-12, and is unchanged from the base standard.

Unchanged rows are not shown in keeping with editorial practice (and noted in the editing instruction). See Table 104-12 of the base standard for the unchanged values on page

4407 line 49 of IEEE P802.3dc D3.0.