IEEE 802.3 Maintenance plenary week meeting unconfirmed minutes July 12, 2000

David Law convened the meeting. Meeting attendance was, Terry Cobb, Bob Noseworthy, Geoff Thompson, Ben Schultz, Tom Mathey.

The process diagram was reviewed. Geoff commented that 'Consult Technical Expert' stage should be change to read 'Consult Technical Experts' as the use of multiple experts is required.

The group then went on to review each change request individually.

Change Request 1000

No Action

Change Request 1001

It was noted that the text 'shall' in the request should be corrected to read 'shall'.

The proposed new wording should match that of 802.1D. Once checked we should the go to ballot. Until then status should remain "I".

Editorial/Technical Technical Ballot Required Yes

Ready for ballot No

New status Incomplete (I)

Change Request 1002

No action

Change Request 1003

No action. Still awaiting more rationale for this request from submitter.

Action: Tom Mathey to contact Rich Seifert to help him draft further text for the 'Rationale for revision' section of the change request.

Change Request 1004

No action. Still awaiting clarification if the note was ever there and if so what it said.

Action: Tom Mathey to contact Geoff Thompson to help him review earlier versions and drafts of the standard to clarify if the note was ever present and if so what it said.

No action. Still awaiting submitter to contact technical experts.

Action: Tom Mathey to consult technical experts Alan Flatman and Pat Thaler. Why is the Clause 10 parallel text not the same.

Change Request 1006

Action: David Law to contact IEEE Editor to ensure that this errata is included in the 2000 edition and is also place on the web site.

Change Request 1007

Action: David Law to contact IEEE Editor to ensure that this errata is included in the 2000 edition and is also place on the web site.

Change Request 1008

Action: David Law to contact IEEE Editor to ensure that this errata is included in the 2000 edition and is also place on the web site.

Change Request 1009

It was noted that this change request related to 7.2.2.2.2 rather than 7.2.2.2 as stated in the change request at present. The request will be updated to reflect the correct subclause.

Action: David Law to contact IEEE Editor to ensure that this errata is included in the 2000 edition and is also place on the web site.

Change Request 1010

No action. Still awaiting confirmation when the duplication of these clauses first occurred and to assurance that when the duplication occurred it did not also cause some other text to be removed

Action: Tom Mathey to contact Geoff Thompson to help him review earlier editions and drafts of the standard to clarify if the note was ever present and if so what it said.

Change Request 1011

Action: David Law to contact IEEE Editor to ensure that this errata is included in the 2000 edition and is also place on the web site.

Change Request 1013

Technical Expert consulted - Geoff Thompson: See previous page for technical verification. The Peak Output Voltage does not exceed 3.65.

Action: David Law to contact IEEE Editor to ensure that this errata is included in the 2000 edition and is also place on the web site.

Editorial/Technical Technical

Ballot Required No Ready for ballot N/A

New status Errata (E)

Change Request 1014

Action: David Law to contact IEEE Editor to ensure that this errata is included in the 2000 edition and is also place on the web site.

Change Request 1015

Action: David Law to correct typo in change request. Then to contact IEEE Editor to ensure that this errata is included in the 2000 edition and is also place on the web site.

Editorial/Technical Editorial
Ballot Required No
Ready for ballot N/A
New status Errata (E)

Change Request 1016

Action: David Law to contact IEEE Editor to ensure that this errata is included in the 2000 edition and is also place on the web site.

Change Request 1017

Action: David Law to do Graphics work for IEEE Editor.

Change Request 1018

As per the e-mail from Bob Noseworthy this change request is incorrect and the text as it stands is correct. The requestor withdrew the request.

Editorial/Technical N/A
Ballot Required N/A
Ready for ballot N/A

New status Withdrawn (W)

Change Request 1020

Action: David Law to contact IEEE Editor to ensure that this errata is included in the 2000 edition and is also place on the web site.

Change Request 1021

No Action taken

Change Request 1022

The correction should read 10**10, not 10**-10. The change request will be corrected. Once corrected the request should go forward as an errata.

Action: David Law to contact IEEE Editor to ensure that this errata is included in the 2000 edition and is also place on the web site.

Change Request 1023

Action: Tom Mathey to contact Rich Seifert to confirm that this is indeed a Errata.

Change Request 1025

Action: David Law to contact IEEE Editor to ensure that this errata is included in the 2000 edition and is also place on the web site.

Change Request 1026

Bob Noseworthy acted as the technical expert for this change. He stated that the symbol should be a not equal symbol. **Action:** David Law to update change request then contact IEEE Editor to ensure that this errata is included in the 2000 edition and is also place on the web site.

Editorial/Technical Editorial
Ballot Required No
Ready for ballot N/A
New status Errata (E)

Change Request 1028

No Action

Change Request 1029

It appears that this is an error between the Sponsor Ballot approved draft (D6.0) and the published document. The state machine should be as balloted.

Action: David Law to contact IEEE Editor to ensure that this errata is included in the 2000 edition and is also place on the web site.

Editorial/Technical Editorial
Ballot Required No
Ready for ballot N/A
New status Errata (E)

Change Request 1030

Action: Bob Noseworthy to contact Sailesh Rao for comment on this proposed change.

Action: David Law to include comment from Sailesh in the request then forward the request for ballot.

Editorial/Technical Technical
Ballot Required Yes
Ready for ballot N/A
New status Ballot (B)

Change Request 1031

Action: David Law to contact IEEE Editor to ensure that this errata is included in the 2000 edition and is also place on the web site.

Change Request 1032

We believe that this is a cross platform problem, refer to voted test pdf printed from a PC. **Warning** for all future annotated scanned drawings to for this type of error.

Action: David Law to contact IEEE Editor to ensure that this errata is included in the 2000 edition and is also place on the web site.

Change Request 1034

Action: David Law to contact IEEE Editor to ensure that this errata is included in the 2000 edition and is also place on the web site.

Change Request 1035

Action: David Law to check earlier editions.

Change Request 1036

New PICS text has been supplied by Terry.

Action: David Law to add new text to change request, after that ready for ballot.

Editorial/Technical Technical
Ballot Required Yes
Ready for ballot N/A
New status Ballot (B)

New Request received since last Maintenance meeting

Change Requests 1037 to 1049

Editorial/Technical Tech
Ballot Required Yes
Ready for ballot Yes

New status Ballot (B)

Change Request 1050

While this appears to be an errata it is of such significance that it needs to be considered at the closing 802.3 plenary.

Editorial/Technical Tech Ballot Required Yes Ready for ballot Yes

New status Ballot (B)

IEEE std 802.3ad MIB Error.

Action: David Law to ensure that there is an errata slip-sheet

in book, a footnote in DS2K and errata on the web.

Editorial/Technical Tech Ballot Required Yes Ready for ballot Yes

New status Ballot (B)

PAR Issue

A PAR will be presented at the 802.3 Closing plenary. A request will be made to forward this to the 802 exec and a request will also be made to go to Working Group ballot, plus any necessary re-circulation ballots, on all requests marked 'B'.

The meeting was adjourned