

-----+
| 8802-3/802.3 REVISION REQUEST |
+-----+

DATE: 8 Nov., 1999
NAME: Thomas Mathey
COMPANY/AFFILIATION: Independent
ADDRESS: 11910 Brookridge Dr.; Saratoga, CA 95070
PHONE: 408-865-1763
FAX:
E-MAIL: tmathey@concentric.net

REQUESTED REVISION: Technical
STANDARD: 802.3, 1998
CLAUSE NUMBER: 32.1
CLAUSE TITLE: Overview
PROPOSED REVISION TEXT:

Super-script is missing

RATIONALE FOR REVISION:

Change 1010 to 10**(10) in sentence 'with a symbol error rate of less than one part in 1010 at the PMA service interface.'

IMPACT ON EXISTING NETWORKS:

None

-----+
| Please attach supporting material, if any |
| Submit to:- Geoffrey O. Thompson, Chair IEEE 802.3 |
| Nortel Networks, Inc. M/S SC5-02 |
| 4401 Great America Parkway |
| P. O. Box 58185 |
| Santa Clara, CA 95052-8185 USA |
| Phone: +1 408 495 1339 FAX: 988 5525 |
| E-Mail: geoff_thompson@baynetworks.com |
+-----+

+----- For official 802.3 use -----+
| REV REQ NUMBER: 1022 |
| DATE RECEIVED: 8 Nov., 1999 |
| EDITORIAL/~~TECHNICAL~~ |
| ACCEPTED/~~DENIED~~ |
| BALLOT REQ'D ~~YES~~/NO |
| COMMENTS: Published IEEE Std 802.3-2000 |
+-----+

-----+
| For information about this Revision Request see - |
| http://www.ieee802.org/3/maint/requests/revision_history.html#REQ1022 |
+-----+