

8802-3/802.3 REVISION REQUEST

DATE: July 12, 2000  
NAME: Geoff Thompson  
COMPANY/AFFILIATION: Nortel Networks  
ADDRESS: PO Box 58185  
Santa Clara, CA 95052-8185  
PHONE: (408) 495 1339  
FAX:  
E-MAIL: thompson@ieee.org

REQUESTED REVISION:  
STANDARD: IEEE Standard 802.3, 1998 Edition  
CLAUSE NUMBER: 1 & 14  
CLAUSE TITLE: References, 10BASE-T

PROPOSED REVISION TEXT:  
Remove all instances of references to ISO/IEC 8877 and replace with IEC-60603-7

RATIONALE FOR REVISION:  
Align with connector specs in subsequent clauses and delete reference to incorrect standard. ISO/IEC 8877 is not a connector spec but rather a pin-out specification for the 8-pin modular jack. IEC-60603-7 was not available at the time the original 10BASE-T was approved

IMPACT ON EXISTING NETWORKS:  
None.

Please attach supporting material, if any  
Submit to:- Geoffrey O. Thompson, Chair IEEE 802.3  
Nortel Networks, Inc. M/S SC5-02  
4401 Great America Parkway  
P. O. Box 58185  
Santa Clara, CA 95052-8185 USA  
Phone: +1 408 495 1339 FAX: 988 5525  
E-Mail: thompson@ieee.org

+----- For official 802.3 use -----+  
REV REQ NUMBER: 1052  
DATE RECEIVED: 12th July, 2000  
~~EDITORIAL~~/TECHNICAL  
ACCEPTED/~~DENIED~~  
BALLOT REQ'D YES/~~NO~~  
COMMENTS: Published IEEE Std 802.3-2002

For information about this Revision Request see -  
[http://www.ieee802.org/3/maint/requests/revision\\_history.html#REQ1052](http://www.ieee802.org/3/maint/requests/revision_history.html#REQ1052)