

+-----+  
| 8802-3/802.3 REVISION REQUEST 1145 |  
+-----+

DATE: 21st May, 2004  
NAME: Thomas Mathey  
COMPANY/AFFILIATION: Independent  
E-MAIL: tmathey@concentric.net

REQUESTED REVISION:  
STANDARD: IEEE Std 802.3-2002  
CLAUSE NUMBER: 14.2.3.2  
CLAUSE TITLE: State diagram timers

PROPOSED REVISION TEXT:

Change text from "Link Fail" to "Link Test Fail" by adding text "Test"

RATIONALE FOR REVISION:

Text for  
"link\_test\_max\_timer. Timer for maximum time input activity can be  
missing before Link Fail state is exited (14.2.1.7)." does not match name  
of state in state diagram.

State name is "Link Test Fail".

For details see attached draft.

IMPACT ON EXISTING NETWORKS:

Editorial change only.

+-----+  
| Please attach supporting material, if any |  
| Submit to:- Bob Grow, Chair IEEE 802.3 |  
| E-Mail: Bob.Grow@intel.com |  
| |  
| +----- For official 802.3 use -----+ |  
| REV REQ NUMBER: 1145 |  
| DATE RECEIVED: 21st May, 2004 |  
| EDITORIAL/~~TECHNICAL~~ |  
| ACCEPTED/~~DENIED~~ |  
| BALLOT REQ'D YES/~~NO~~ |  
| COMMENTS: 08-Mar-06 Ver: D2.0 Status: P |  
+-----+

| For information about this Revision Request see - |  
| [http://www.ieee802.org/3/maint/requests/revision\\_history.html#REQ1145](http://www.ieee802.org/3/maint/requests/revision_history.html#REQ1145) |

*Change timer 'link\_test\_max\_timer' of subclause 14.2.3.2 as follows:*

**link\_test\_max\_timer.** Timer for maximum time input activity can be missing before Link TestFail state is exited (14.2.1.7).

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36  
37  
38  
39  
40  
41  
42  
43  
44  
45  
46  
47  
48  
49  
50  
51  
52  
53  
54