

-----+
| 8802-3/802.3 REVISION REQUEST 1192 |
+-----+

DATE: 2nd Dec, 2006
NAME: Yair Darshan
COMPANY/AFFILIATION: PowerDsine
E-MAIL: yaird@powerdsine.com

REQUESTED REVISION:
STANDARD: IEEE Std 802.3-2005
CLAUSE NUMBER: Fig 33C-2
CLAUSE TITLE: Test configuration PSE-B

PROPOSED REVISION TEXT:

Change from "dv/dt<35mA/ s"
To "dv/dt<35mA/ms"

RATIONALE FOR REVISION:

Editing error.

IMPACT ON EXISTING NETWORKS:

No impact on current hardware. The error is in the Informative section.

-----+
| Please attach supporting material, if any |
| Submit to:- Bob Grow, Chair IEEE 802.3 |
| E-Mail: Bob.Grow@intel.com |
| |
| +----- For official 802.3 use -----+ |
| REV REQ NUMBER: 1192 |
| DATE RECEIVED: 2nd Dec, 2006 |
| ~~EDITORIAL/TECHNICAL~~ |
| ACCEPTED/DENIED |
| BALLOT REQ'D YES/~~NO~~ |
| COMMENTS: 19-Jan-07 Ver: D1.1 Status: B |
+-----+

| For information about this Revision Request see - |
| http://www.ieee802.org/3/maint/requests/revision_history.html#REQ1192 |
+-----+