

+-----+
| 8802-3/802.3 REVISION REQUEST 1199 |
+-----+

DATE: 20th Sep, 2008
NAME: Geoff Thompson
COMPANY/AFFILIATION:Nortel
E-MAIL:thompson@ieee.org

REQUESTED REVISION:
STANDARD: 802.3 2008
CLAUSE NUMBER: 30
CLAUSE TITLE: Management

PROPOSED REVISION TEXT:
Not specified, rather this request is in the form of an editorial instruction

Effectively change text that says "this subclause" in each of the definitions

FROM
"this subclause"
TO
"30.n.n.n (where 30.n.n.n is the actual subclause in which the object is defined)
(the actual clause number should be a FrameMake link).

RATIONALE FOR REVISION:
Current text is incorrect.

IMPACT ON EXISTING NETWORKS:
Editorial correction only

+-----+
| Please attach supporting material, if any
| Submit to:- David Law, Chair IEEE 802.3
| E-Mail: David_Law@ieee.org
|
| and copy:- Wael William Diab, Vice-Chair IEEE 802.3
| E-Mail: wdiab@broadcom.com
|
| +----- For official 802.3 use -----+
| REV REQ NUMBER: 1199
| DATE RECEIVED: 20th Sep, 2008
| EDITORIAL/TECHNICAL
| ACCEPTED/DENIED
| BALLOT REQ'D YES/NO
| COMMENTS: XX-Xxx-XX Ver: D1.0 Status: R
+-----+

+-----+
| For information about this Revision Request see -
| http://www.ieee802.org/3/maint/requests/revision_history.html#REQ1199
+-----+