

+-----+
| 8802-3/802.3 REVISION REQUEST 2015 |
+-----+

DATE: 12th Nov, 2009
NAME: D. Matthew Landry
COMPANY/AFFILIATION: EMI
E-MAIL: dmlandry@ieee.org

REQUESTED REVISION:
STANDARD: IEEE Std 802.3at-2009
CLAUSE NUMBER: 33.2.7
CLAUSE TITLE: Power supply output

PROPOSED REVISION TEXT:
Table 33-11, item 7, Overload current detection range -- Min value should be PClass/VPort_PSE.

RATIONALE FOR REVISION:
The division symbol (/) was dropped during the comment resolution process between P802.3at D4.0 and D4.1.

IMPACT ON EXISTING NETWORKS:
As the current entry is essentially meaningless without the division symbol, presumably none.

+-----+
| Please attach supporting material, if any |
| Submit to:- David Law, Chair IEEE 802.3 |
| and copy:- Wael William Diab, Vice-Chair IEEE 802.3 |
| At:- E-Mail: stds-802-3-maint-req@ieee.org |
| +----- For official 802.3 use -----+ |
| REV REQ NUMBER: 2015 |
| DATE RECEIVED: 12th Nov, 2009 |
| EDITORIAL/TECHNICAL |
| ACCEPTED/DENIED |
| BALLOT REQ'D YES/NO |
| COMMENTS: XX-Xxx-XX Ver: D1.0 Status: R |
+-----+

+-----+
| For information about this Revision Request see - |
| http://www.ieee802.org/3/maint/requests/revision_history.html#REQ2015 |
+-----+