

```

1  +-----+
2  |               8802-3/802.3 REVISION REQUEST               |
3  +-----+
4  DATE: 12/10/19
5  NAME: Brett McClellan
6  COMPANY/AFFILIATION: Marvell Semiconductor
7  E-MAIL: bmc@marvell.com
8
9  REQUESTED REVISION:
10 STANDARD: 802.3-2018
11 CLAUSE NUMBER: 55.4.6.3
12 CLAUSE TITLE: Link Monitor state diagram
13
14 PROPOSED REVISION TEXT:
15
16 change "(Figure 28-16)." to "(Figure 28-18)."
17
18 RATIONALE FOR REVISION:
19
20 This was an error in the integration of 802.3an into the base standard.
21 Two new figures were inserted into Clause 28 and this reference was not
22 updated as the figures were renumbered.
23
24
25 IMPACT ON EXISTING NETWORKS:
26 No impact to existing networks.
27
28
29 +-----+
30 | Please attach supporting material, if any                    |
31 | Submit to:- David Law, Chair IEEE 802.3                    |
32 | and copy:- Adam Healey, Vice-Chair IEEE 802.3              |
33 |                                                              |
34 | At:- E-Mail: stds-802-3-maint-req@ieee.org                  |
35 |                                                              |
36 |           +----- For official 802.3 use -----+         |
37 |           | REV REQ NUMBER: 1351                          |         |
38 |           | DATE RECEIVED: 10 December, 2019              |         |
39 |           | EDITORIAL/TECHNICAL                            |         |
40 |           | ACCEPTED/DENIED                                |         |
41 |           | BALLOT REQ'D      YES/NO                        |         |
42 |           | COMMENTS:                                        |         |
43 +-----+
44 | For information about this Revision Request see -           |
45 | http://www.ieee802.org/3/maint/requests/revision\_history.html#REQ1351 |
46 +-----+

```