

MJH01 Section: 9.1 Line: 633 Severity: A/C
Type: ED

Concern:

Reference Error

Solution:

Replace 0) with 9.7.1)

Note: I believe 9.7.1 is a better reference than
9.1.6.2 which points to 9.7.
9.7.1 describes the C-Port Repeat Path

MJH02 Section: 9.1 Line: 634 Severity: A/C
Type: ED

Concern:

Reference Error

Solution:

Replace See (0) with See (9.3.3.2)

Note: 9.3.3.2 describes flag FPBNT

MJH03 Section: 9.3 Line: 270 Severity: A/C
Type: ED

Concern:

Spelling

Solution:

Replace C-Operational with C-Port Operational

Draft 7.1 Dec 1996

MJH04 Section: 9.2 Line: 387 Severity: A/C
Type: ED

Concern:

Incorrect Reference

Solution:

Change

<< This Transition is executed by 9.6.2.7. >>
to

<< This Transition is executed by 9.6.2.1. >>

(ref page 9.6-8)

MJH05 Section: 9.3 Line: 227 Severity: A/C
Type: TECH

Concern:

Incorrect action specified

Solution:

Replace

a Ring Purge MAC frame

with

a Claim Token MAC frame

<REF S/T JKN/1006, page 9.3-15)

MJH06 Section: 9.4 Line: 205 Severity: A/C
Type: EDITORIAL

(page 9.4-16, S/t M10A/175)

Concern:

S/T incorreced identified

Solution:

on S/T M10A, REF 175, relabel S/T to M10B.

(REF: ISO 8802-5, 802.5s, figure 9.4-4 Monitor FSM
this document)

MJH07 Section: 9.4 Line: 205 Severity: A/C
Type: EDITORIAL

(page 9.4-17, S/t M10B/177)

Concern:

S/T incorreced identified

Solution:

on S/T M10B, REF 177, relabel S/T to M10A.

(REF: ISO 8802-5, 802.5s, figure 9.4-4 Monitor FSM
this document)

MJH08

Table on page 9.3-24 change VAULE to VALUE