P802.1ASdm-Rev/D0.2 Editor's Report

Proposed Comment Resolution for TG Ballot

Version 6

Geoffrey M. Garner Huawei (Consultant)

gmgarner@alum.mit.edu

IEEE 802.1 TSN TG 2021.06.07

Ballot Statistics

□Thanks to all who reviewed the document and commented

Category	All respondents	
	Total	Percent
Yes (voters)	8	40.00
No (voters)	12	60.00
Voting Yes or No	20	100
Abstain Time	3	
Abstain Expertise	9	
Abstain Total	12	37.5
Respondents	33	
Voting Members	32	100
Non-voting member commenters	1 (voted no)	
Number of Commenters	18	
Number of Comments	148	
TR	55	
Т	6	
ER	67	
E	20	

- ☐ In what follows, grouped comments are shown together in parentheses
- □Editorial Comments (Category E or ER) that are, in the judgement of the editor, trivial (35 comments)
 - •All the following comments will be accepted or accepted in principle, and will not be discussed unless someone indicates a desire to discuss them (they will be left in proposed mode for an adequate time period for participants to review them)
 - •(6, 110), (7, 40, 111), 23, 24, 25, 29, 30, (31, 62, 119), 35, (36, 55, 76), (39, 78),41, 43, (51, 52, 53, 61, 63), 58, 59, 60, 74, 90, 105, 130, 145, 146,
- ☐ The comments on the following pages will be discussed.
 - ■Note that many of the ones marked E or ER are nontrivial and must be discussed in detail (even though they are marked E or ER)
 - •Note that the listed topics are not necessarily full descriptions of the comments; they are mainly to aid the editor in the comment resolution

□Comments to be discussed (113 comments):

- ■Why is the scope changing: (1, 73, 85)
- ■Why are maintenance items not in Cor1: 2
- ■Elimination of references to 60802: (3, 100)
- ■Event message terminology, event messages in HotStandbySystem state machine, and criteria for isCapable transition from TRUE to FALSE : (4, 12, 79, 80)
- syncReceiptTimeoutTime: (5, 71)
- ■Subclause organization: (8, 9, 21, 72, 136)
- ■Why must all available ports be asCapable for isCapable to be TRUE: 10
- ■Criteria for SYNCED and NOT_QUALITY: (11, 14, 17, 57, 64, 103)
- ■slaveP changing to/from -1 in HotStandbySystem state machine: 13
- ■Nomenclature "HotStandby" instead of "60802": (15, 19, 42, 65, 68, 69, 70, 86, 87, 94, 99, 112, 121, 122, 124, 125, 126, 132)
- ■References to global variables in state machines, instead of managed objects: (16, 22, 67, 102)
- ■Use of italics for hot standby related names: 18, 66, 96, 104, 116, 123

□Comments to be discussed (Cont.):

- ■Reverting via "human being" vs "external entity" vs "higher-layer entity", etc.: (20, 26, 56, 133, 134, 141)
- ■Use of term "timescale": 33
- Clarification of description of HotStandbySystem entity: (37, 38, 118), 144
- Split functionality (should it be included): 44
- ■Description of actions caused by HotStandbySystem entity in 17.12: (45, 46, 47, 48, 84)
- ■MIB modifications: 49
- ■Editing instructions to change "domain number" to "domainNumber": 50
- ■Errata page link: <mark>54</mark>
- ■Reference to figure 10-1: <mark>75</mark>
- ■Use of PTP versus gPTP: (77, 97)
- Nomenclature: FAULT versus NOT REDUNDANT: 81
- Description of holdover: (82, 107, 113)
- •Action by HotStandbySystem entity when the system is a slave and in FAULT state: 83
- Addition of hotStandbySystemReset variable: 88
- Recovery of HotStandbySystem: 89

□Comments to be discussed (Cont.):

- Addition of editor's notes to indicate changes and, where relevant, maintenance items: (91, 92, 93, 120, 129,131)
- ■"Seamless" terminology: (114, 115)
- ■Clarification of HotStandbyInstance: 117, 135, 137, 138, (139, 140), 142, 143
- Addition of "N/A []" to PICS: 127
- ■Backward compatibility of 802.1ASdm with 802.1AS-2011: (128, 148)
- ■Miscellaneous: 27, 28, 32, 34, (98, 101), 106, (108, 109), 147
- Redrawing of figures for clarity: 95