

## IEEE 802.1 Maintenance

### Meeting

June 27<sup>th</sup>, 2017

11:00am-12:00pm Eastern – Minutes v1 (John Messenger)

Attendees: Parsons, Glenn; Messenger, John; Rouyer, Jessy; Gunther, Craig; Reilly, Denis; McIntosh, James; Gravel, Mark; Hamilton, Mark; Cummings, Rodney; Haddock, Steve; McBeath, Tom; Finn, Norm

The chair, John Messenger, introduced the agenda, showed the patent policy slides and made the call for patents. There were no responses.

1. John presented the list of current vehicles (drafts) used for implementing maintenance items, and the current numerical status of maintenance items in the database. Details in the Maintenance Session Slides.
  2. John presented the [Editor's Report](#) for 802.1Q-Rev/D1.4.
  3. Comment resolution was performed on 802.1Q-Rev/D1.4 following the recent WG recirculation ballot. The single technical comment was withdrawn by the commentor (Stephen Haddock) and he plans to resubmit it at Sponsor ballot. Three editorial comments regarding formatting of EtherType values will be dealt with via the cover letter of the Sponsor ballot, stating that these editorial changes will be made during the sponsor ballot process.
  4. New maintenance items were discussed:
    - a. ~~0183: [CFM OpCodes](#)~~ (not discussed)
    - b. 0186: [Buffer occupancy managed objects](#). Though this was rejected as being an enhancement request, it was noted that the chair or vice-chair should submit this as a sponsor ballot comment on behalf of the commentor (Tom McBeath) as he is not a member of the sponsor ballot pool.
    - c. 0187: [Port counter for FCS errors](#)
  5. See the session slides (<http://ieee802.org/1/files/public/docs2017/maint-messenger-session-0617-v3.pdf>) and web-site (<http://www.ieee802.org/1/maint.html>) for further details and discussion.
-