DATE: March 18, 2014 NAME: Norman Finn

COMPANY/AFFILIATION: Cisco Systems

E-MAIL: nfinn@cisco.com

REQUESTED REVISION: STANDARD: 802.1AB-2009 CLAUSE NUMBER: E.8.1

CLAUSE TITLE: aggregation status

## RATIONALE FOR REVISION:

Table E.2 is wrong. It numbers the bits 0-7, and Figure D.2 numbers them 1-8. This is not a major problem; most readers should be able to detect the blunder and do the right thing. However, this TLV is now documented in three places:

- < 802.1AB-2009, as just described</pre>
- $\,\,$  P802.1AX-REV, corrected and extended. This standard is starting sponsor ballot.

## PROPOSED REVISION TEXT:

Delete section E.8 and renumber the remaining sections of Annex E. Replace all references to E.8 in the document with the corresponding references to 802.1AX-REV Annex F.1.

IMPACT ON EXISTING NETWORKS:

None.

+.	
	Please attach supporting material, if any Submit to:- Tony Jeffree, Chair IEEE 802.1
	<u> </u>
	and copy:- Glenn Parsons, Vice-Chair IEEE 802.1
	E-Mail: stds-802-1-maint-reg@ieee.org
Ì	
	++ For official 802.1 use+
	REV REQ NUMBER: 0133
	DATE RECEIVED: Mar. 18 2014
	EDITORIAL/TECHNICAL
	ACCEPTED/DENIED
	BALLOT REQ'D YES/NO
	Status: R
	++
+.	