

IEEE 802.17 Maintenance Request 0016

MR number 0016 Classification Technical Date received 3/11/2005 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 476 Subclause D.6 Figure _____ Table _____

Surname Holness Given Name Marc

Perceived Problem [If more space is needed, please provide an additional file, preferably as plain text.]

Range of rprIfKeepaliveTimeout object is (2..50) ms. However the state machine description provided in Section 11.6.2.2 states that the range should be (2..200) ms. This inconsistency needs to be resolved.

Proposed Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

Change range of rprIfKeepaliveTimeout object to (2..200).

Rationale For Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

Consistency within the specifications.

Remedy's Effect On Existing Equipment [If more space is needed, provide an additional file, preferably as plain text.]

No impact.

When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.