

IEEE 802.17 Maintenance Request 0041

MR number 0041 Classification Technical Date received 3/13/2005 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 489 Subclause D.6 Figure _____ Table _____

Surname Lemon Given Name John

Perceived Problem [If more space is needed, please provide an additional file, preferably as plain text.]

RprTopolmageEntry is missing an attribute corresponding to spanEdge[ri].

Proposed Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

Add an attribute corresponding to spanEdge[ri].

Rationale For Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

This needs to be reported in the MIB.

Remedy's Effect On Existing Equipment [If more space is needed, provide an additional file, preferably as plain text.]

None.

When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.