

IEEE 802.17 Maintenance Request 0059

MR number 0059 Classification Technical Date received 4/5/2005 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 157 Subclause 7.7.1.2.5 Figure _____ Table _____

Surname James Given Name David

Perceived Problem [If more space is needed, please provide an additional file, preferably as plain text.]

The text notes that:

>>For wrapping rings, if the frame is not replicated, the we field is set.

>>For wrapping rings, if the frame is replicated, the we field is not set.

>>For steering rings, the we field has no meaning and is not set.

What about a center-wrapping ring with bidirectional flooding.

Wouldn't that still be replicated with the we==1? I would have

thought that was necessary to be protected.

Proposed Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

Correct text as appropriate.

Rationale For Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

Remedy's Effect On Existing Equipment [If more space is needed, provide an additional file, preferably as plain text.]

When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.