IEEE 802.17 Maintenance Request 0095

MR number	0095	Classification	Technical	Date received	2/12/2006	Reserved for of	ficial 802.17 use
Standard	802.17-200)4 Page	142 Subcl	ause 7.6.3.9.	4 Figure	Table	7.23
Surname	Bruckman Given Name Leon			Leon			

 Perceived Problem
 [If more space is needed, please provide an additional file, preferably as plain text.]

 In row 7.23-4 in the condition column wrong parameter name: "frame.sa", since the frame.ft is Firness, then the sa is saCompact

Proposed Remedy [If more space is needed, please provide an additional file, preferably as plain text.] Replace "frame.sa" with: "frame.saCompact"

Rationale For Remedy

[If more space is needed, please provide an additional file, preferably as plain text.]

Consistency

Remedy's Effect On Existing Equipment

[If more space is needed, provide an additional file, preferably as plain text.]

No effect

When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.