

Editor's report for 802.3aq Task Force meeting, March 2006, Denver, Colorado.

44 comments received, from SA members, on Draft 3.1

5 T, 18 TR,

16 E, 3 ER,

2GR

From 10 comment contributors:

COORDINATION, EDITORIAL	1
DAWE, PIERS	27
CUNNINGHAM, DAVID	2
DUDEK, MICHAEL T	1
BHOJA, SUDEEP	1
GHIASI, AL	1
Inano, Shigeru	1
LINDSAY, THOMAS A	4
EWEN, JOHN F	1
GROW, ROBERT M	5

Editor's report for 802.3aq Task Force meeting, March 2006, Denver, Colorado.

Proposed comment resolution agenda.

Wednesday 8th March		
E, ER and GR comments: 1, 40, 41, 42, 44. 16 E comments – Proposed motion in comment 13	PRBS9: 28, 36, 37	
Break		
Noise component of Comp. Stressed Receiver Test. David C (20)., Piers D (30). and Badri G. (15) presentations. Comments 3, 5, 6, 7, 29, 30	Split symmetric receiver test stressor: Paul K. (10) and John A. (10) presentations. John A. 2, (3), 4, 8, 11, (29), (30)	
Lunch		
TWDP value and Tx Power: Tom L. (20) Presentation. 31, 34, 35, 38, 39	Jitter: 32, 33.	
Break		
Operating Range: 9, 10	Installation (use of patch cords): 12	