



TELECOMMUNICATIONS  
INDUSTRY ASSOCIATION

1320 N. Courthouse Rd., Suite 200  
Arlington, VA 22201 USA

Tel: +1.703.907.7700

Fax: +1.703.907.7727

[www.tiaonline.org](http://www.tiaonline.org)

## TR-42 CORRESPONDENCE

Ray Emplit, TIA TR42 Engineering Committee Chair,  
[remlit@harger.com](mailto:remlit@harger.com)

Date: September 3, 2015

To: David Chalupsky, IEEE 802.3bz Task Force Acting Chair, [david.chalupsky@intel.com](mailto:david.chalupsky@intel.com)

Cc: David Law, IEEE 802.3 Working Group Chair, [dlaw@hp.com](mailto:dlaw@hp.com)  
Adam Healey, IEEE 802.3 Working Group Vice Chair, [adam.healey@avagotech.com](mailto:adam.healey@avagotech.com)  
Steve Carlson, IEEE 802.3 Working Group Executive Secretary, [scarlson@ieee.org](mailto:scarlson@ieee.org)  
Pete Anslow, IEEE 802.3 Working Group Secretary, [panslow@ciena.com](mailto:panslow@ciena.com)  
Greg Sandels, TIA TR-42 Engineering Committee Vice Chair, [gsandels@ofsoptics.com](mailto:gsandels@ofsoptics.com)  
Jonathan Jew, TIA TR-42 Engineering Committee Secretary, [jew@j-and-m.com](mailto:jew@j-and-m.com)  
Wayne Larsen, TIA TR-42.7 Subcommittee Chair, [wlarsen@commscope.com](mailto:wlarsen@commscope.com)  
Valerie Maguire, TIA Incoming Liaison to IEEE 802.3 Working Group,  
[valerie\\_maguire@siemon.com](mailto:valerie_maguire@siemon.com)  
Chris DiMinico, IEEE 802.3 Working Group Incoming Liaison to TIA, [cdiminico@ieee.org](mailto:cdiminico@ieee.org)  
Germaine Palangdao, TIA, [GPalangdao@tiaonline.org](mailto:GPalangdao@tiaonline.org)  
Teesha Jenkins, TIA, [tjenkins@tiaonline.org](mailto:tjenkins@tiaonline.org)

RE: TR-42 Liaison to IEEE 802.3bz Task Force re TSB-5021 Draft 0.1d

Dear Mr. Chalupsky:

Please find attached draft 0.1d of our Technical Systems Bulletin, entitled *Guidelines for the Assessment and Mitigation of Installed Cabling to Support 2.5GBASE-T and 5GBASE-T*, to be published as TIA TSB-5021. Please note that this is an early draft and has not been subject to the TIA public comment process.

Sincerely,

Ray Emplit  
Chair, TIA TR-42 Engineering Committee

Attachment