

8802-3/802.3 REVISION REQUEST

DATE: 8 Nov., 1999  
NAME: Thomas Mathey  
COMPANY/AFFILIATION: Independent  
ADDRESS: 11910 Brookridge Dr.; Saratoga, CA 95070  
PHONE: 408-865-1763  
FAX:  
E-MAIL: tmathey@concentric.net

REQUESTED REVISION: Editorial  
STANDARD: 802.3, 1998  
CLAUSE NUMBER: 23.2.1.1 & 23.4.1.1  
CLAUSE TITLE: PCSReset function  
PROPOSED REVISION TEXT:

Incorrect symbol '<='

RATIONALE FOR REVISION:

In sentence 'sets pcs\_reset <= ON' to '='.  
Same change for paragraph 23.4.1.1

IMPACT ON EXISTING NETWORKS:

None

Please attach supporting material, if any  
Submit to:- Geoffrey O. Thompson, Chair IEEE 802.3  
Nortel Networks, Inc. M/S SC5-02  
4401 Great America Parkway  
P. O. Box 58185  
Santa Clara, CA 95052-8185 USA  
Phone: +1 408 495 1339 FAX: 988 5525  
E-Mail: geoff\_thompson@baynetworks.com

+----- For official 802.3 use -----+  
REV REQ NUMBER: 1018  
DATE RECEIVED: 8 Nov., 1999  
EDITORIAL/~~TECHNICAL~~  
ACCEPTED/~~DENIED~~  
BALLOT REQ'D ~~YES~~/NO  
COMMENTS: Published IEEE Std 802.3-2000

For information about this Revision Request see -  
[http://www.ieee802.org/3/maint/requests/revision\\_history.html#REQ1018](http://www.ieee802.org/3/maint/requests/revision_history.html#REQ1018)