+----+ 8802-3/802.3 REVISION REQUEST

DATE: July 10, 2001 NAME: David Law

COMPANY/AFFILIATION: 3Com

ADDRESS: Princes Exchange

1 Earl Grey Street

Edinburgh, UK, EH3 9BN

PHONE: +44 131 659 8218 FAX: +44 131 659 8001 David_Law@3Com.com E-MAIL:

REQUESTED REVISION:

IEEE Std. 802.3-2000 STANDARD:

CLAUSE NUMBER: Annex 30C.6
CLAUSE TITLE: Definitions for Link Aggregation MIB

PROPOSED REVISION TEXT:

Correct the following 3 errors related to the SNMP MIB published in 30C.6. In addition update the URL to use www.ieee802.org rather than grouper.ieee.org previously used.

[1] Restore the following notes -

NOTES

- 1 As this text goes to publication it is believed that the identifier "802dot3" i.e., in the context 802dot3 (10006), violates ASN rules ref ASN 1 (X.208 Section 8.3) and will therefore produce a syntax error when compiled. IEEE is taking action to change this identifier to "ieee802dot3" as quickly as possible.
- 2 The ASCII for 30C.6 is available from http://www.ieee802.org/3/publication/index.html
- [2] Restore the following footnotes -
- 3 MIB definitions are available at http://www.ietf.org/.
- 4 Copyright release for SNMP MIB: Users of this standard may freely reproduce the SNMP MIB in this annex so it can be used for its intended purpose.
- [3] The MIB should be published using a non-proportional font such as Courier.

RATIONALE FOR REVISION:

This text was approved as part of the IEEE P802.3ad project and published in IEEE Std. 802.3ad-2000 yet is missing from the consolidated edition IEEE Std. 802.3-2000. In addition the opportunity should be taken to update the URL to the latest version.

IMPACT ON EXISTING NETWORKS:

None.

```
+-----
Please attach supporting material, if any
| Submit to:- Geoffrey O. Thompson, Chair IEEE 802.3
            Nortel Networks, Inc. M/S SC5-02
            4401 Great America Parkway
            P. O. Box 58185
            Santa Clara, CA 95052-8185 USA
            Phone: +1 408 495 1339 FAX: 988 5525
            {\tt E-Mail: gthompso@nortelnetworks.com}
           +----- For official 802.3 use -----+
             REV REQ NUMBER: 1077
              DATE RECEIVED: 18 July, 2001
              EDITORIAL/TECHNICAL
              ACCEPTED/<del>DENIED</del>
              BALLOT REQ'D YES/NO
             COMMENTS: Published IEEE Std 802.3-2002
For information about this Revision Request see -
```

http://www.ieee802.org/3/maint/requests/revision_history.html#REQ1077