

+-----+  
| 8802-3/802.3 REVISION REQUEST 1259 |  
+-----+

DATE: 28th May, 2014  
NAME: Eric Lynskey  
COMPANY/AFFILIATION: Broadcom Corporation  
E-MAIL: elynskey@broadcom.com

REQUESTED REVISION:  
STANDARD: IEEE Std 802.3-2012  
CLAUSE NUMBER: 76.3.3.6  
CLAUSE TITLE: 66B/64B Decode

PROPOSED REVISION TEXT:

See 49.2.11 Receive process. The decoder shall perform functions specified in the state diagram shown in Figure 49-15.

Should be changed to:

See 49.2.11 Receive process. The decoder shall perform functions specified in the state diagram shown in Figure 49-17.

RATIONALE FOR REVISION:

When IEEE 802.3av was originally published, the correct reference in Clause 49 was Figure 49-15. Subsequent revisions of the Standard have updated the figure numbers in Clause 49, but not in Clause 76. The intent was to point to the Receive state diagram, which is currently in Figure 49-17.

IMPACT ON EXISTING NETWORKS:

None.

+-----+  
| Please attach supporting material, if any |  
| Submit to:- David Law, Chair IEEE 802.3 |  
| and copy:- Adam Healey, Vice-Chair IEEE 802.3 |  
| At:- E-Mail: stds-802-3-maint-req@ieee.org |  
| +----- For official 802.3 use -----+ |  
| REV REQ NUMBER: 1259 |  
| DATE RECEIVED: 28th May, 2014 |  
| EDITORIAL/TECHNICAL |  
| ACCEPTED/DENIED |  
| BALLOT REQ'D YES/NO |  
| COMMENTS: XX-Xxx-XX Ver: D1.0 Status: R |  
+-----+

| For information about this Revision Request see - |  
| [http://www.ieee802.org/3/maint/requests/revision\\_history.html#REQ1259](http://www.ieee802.org/3/maint/requests/revision_history.html#REQ1259) |  
+-----+