

```

1  +-----+
2  |                8802-3/802.3 REVISION REQUEST                |
3  +-----+
4
5  DATE:                November 23, 2015
6  NAME:                George Zimmerman
7  COMPANY/AFFILIATION: CME Consulting, Inc.
8  E-MAIL:              george@cmephyconsulting.com
9
10 REQUESTED REVISION:
11   STANDARD:          IEEE Std 802.3-2015
12   CLAUSE NUMBER:    45.2.1.74, 45.2.1.75, 45.2.1.76, and 45.2.1.77
13   CLAUSE TITLE:     Management Data Input/Output Interface
14
15 PROPOSED REVISION TEXT:
16 Replace " MA_Training_Init_S" with " PMA_Training_Init_S" in text of
17 45.2.1.74, 45.2.1.75, 45.2.1.76, and 45.2.1.77 (identical text)
18
19 RATIONALE FOR REVISION: There is no state " MA_Training_Init_S" in
20 The referenced clause 55.4.3.1, but "PMA_Training" is there and is
21 Clearly what is intended. This is an obvious typo.
22
23 IMPACT ON EXISTING NETWORKS: None.
24
25
26 +-----+
27 |Please attach supporting material, if any                       |
28 |Submit to:- David Law, Chair IEEE 802.3                       |
29 |and copy:- Adam Healey, Vice-Chair IEEE 802.3                |
30 |                                                               |
31 |At:- E-Mail: stds-802-3-maint-req@ieee.org                    |
32 |                                                               |
33 |                +----- For official 802.3 use -----+    |
34 |                | REV REQ NUMBER: 1292                       |    |
35 |                | DATE RECEIVED: 23-Nov-15                   |    |
36 |                | EDITORIAL/TECHNICAL                       |    |
37 |                | ACCEPTED/DENIED                            |    |
38 |                | BALLOT REQ'D YES/NO                        |    |
39 |                | COMMENTS:                                  |    |
40 +-----+
41 | For information about this Revision Request see -           |
42 | http://www.ieee802.org/3/maint/requests/revision\_history.html#REQ1292 |
43 +-----+
44

```