

+-----+
| IEEE 802.1 REVISION REQUEST 0061 |
+-----+

DATE: 31 October 2012
NAME: Paul Woods
COMPANY/AFFILIATION: Aptina, LLC
E-MAIL: pwoods@aptina.com<<mailto:pwoods@aptina.com>> (via Dave Olsen
dolsen@harman.com<<mailto:dolsen@harman.com>>)

REQUESTED REVISION:
STANDARD: 802.1AS-2011
CLAUSE NUMBER: 10.2.6.1.1
CLAUSE TITLE:

RATIONALE FOR REVISION:

10.2.6.1.1: The name rcvdPSSync is used in 10.2.11.1.1 and 10.2.12.1.1 for different variables, which is confusing.

PROPOSED REVISION TEXT:

See Above

IMPACT ON EXISTING NETWORKS:

None. Changes could help implementers avoid confusion.

+-----+
| Please attach supporting material, if any |
| Submit to:- Tony Jeffree, Chair IEEE 802.1 |
| and copy:- Glenn Parsons, Vice-Chair IEEE 802.1 |
| E-Mail: stds-802-1-maint-req@ieee.org |
| |
| +----- For official 802.1 use -----+ |
| | REV REQ NUMBER: 0061 | |
| | DATE RECEIVED: 11/01/2012 | |
| | EDITORIAL/TECHNICAL | |
| | ACCEPTED/DENIED | |
| | BALLOT REQ'D YES/NO | |
| | Status: R | |
| +-----+ |
+-----+