

+-----+  
| IEEE 802.1 REVISION REQUEST 0067 |  
+-----+

DATE: 31 October 2012  
NAME: Paul Woods  
COMPANY/AFFILIATION: Aptina, LLC  
E-MAIL:  
[pwoods@aptina.com](mailto:pwoods@aptina.com)<<mailto:pwoods@aptina.com>> ( via Dave Olsen  
[dolsen@harman.com](mailto:dolsen@harman.com)<<mailto:dolsen@harman.com>>)

REQUESTED REVISION:  
STANDARD: 802.1AS-2011  
CLAUSE NUMBER: 10.3.12.1.4  
CLAUSE TITLE:

RATIONALE FOR REVISION:

10.3.12.1.4: the description of updRolesTree() is confusing---needs some diagrams

PROPOSED REVISION TEXT:

See Above

IMPACT ON EXISTING NETWORKS:

None. Changes could help implementers avoid confusion.

+-----+  
| Please attach supporting material, if any |  
| Submit to:- Tony Jeffree, Chair IEEE 802.1 |  
| and copy:- Glenn Parsons, Vice-Chair IEEE 802.1 |  
| E-Mail: [stds-802-1-maint-req@ieee.org](mailto:stds-802-1-maint-req@ieee.org) |  
| |  
| +----- For official 802.1 use -----+ |  
	REV REQ NUMBER: 0067	
	DATE RECEIVED: 11/01/2012	
	EDITORIAL/TECHNICAL	
	ACCEPTED/DENIED	
	BALLOT REQ'D YES/NO	
	Status: R	
+-----+		
+-----+