

+-----+
| IEEE 802.1 REVISION REQUEST 0084 |
+-----+

DATE: 31 October 2012
NAME: Paul Woods
COMPANY/AFFILIATION: Aptina, LLC
E-MAIL: pwoods@aptina.com<<mailto:pwoods@aptina.com>> (via Dave Olsen
dolsen@harman.com<<mailto:dolsen@harman.com>>)

REQUESTED REVISION:
STANDARD: 802.1AS-2011
CLAUSE NUMBER: General
CLAUSE TITLE:

RATIONALE FOR REVISION:

General: There needs to be more clarity about what parts can be omitted for a one-port, listener-only endpoint. For instance, in Figure 10-2, I believe that PortSyncSyncSend and MDSyncSend are not needed in that case (although PortSyncSyncReceive then needs to handle an action that PortSyncSyncSend performs).

PROPOSED REVISION TEXT:

See Above

IMPACT ON EXISTING NETWORKS:

None. Changes could help implementers avoid confusion.

+-----+
| Please attach supporting material, if any |
| Submit to:- Tony Jeffree, Chair IEEE 802.1 |
| and copy:- Glenn Parsons, Vice-Chair IEEE 802.1 |
| E-Mail: stds-802-1-maint-req@ieee.org |
| |
| +----- For official 802.1 use -----+ |
| | REV REQ NUMBER: 0084 | | |
| | DATE RECEIVED: 11/01/2012 | | |
| | EDITORIAL/TECHNICAL | | |
| | ACCEPTED/DENIED | | |
| | BALLOT REQ'D YES/NO | | |
| | Status: R | | |
| +-----+ |
+-----+