

Report from Maintenance Group

- **Received 63 letter ballot comments**
 - Technical: 21
 - technical: 17
 - Editorial: 22
 - Editorial masquerading as Technical: 3
- **All comments resolved**
 - Accepted: 52
 - Declined: 6
 - Withdrawn: 3
 - Obsolete: 2
- **All changes are available**

Informed Technology, Inc.

doc: IEEE 802.11 98/52

Issues

- **Addition of three new regulatory domains with new hopping sequences defined for FH PHY**
- **Removal of “PHY constants” from the MIB and definition of a new PHY service primitive to provide the identical information to the MAC**
- **Addition of several new attributes to the MIB**
 - dot11PowerManagementMode, dot11DesiredSSID, dot11DesiredBSSType, dot11OperationalRateSet, dot11BeaconPeriod, dot11DTIMPeriod, dot11AssociationResponseTimeOut,

Informed Technology, Inc.

doc: IEEE 802.11 98/52