

IEEE 802.17 Maintenance Request 0013

MR number 0013 Classification Technical Date received 3/11/2005 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 472 Subclause D.6 Figure _____ Table _____

Surname Jones Given Name Peter

Perceived Problem [If more space is needed, please provide an additional file, preferably as plain text.]

There are a number of issues with the MIB text not conforming to the main clauses in the standard, having invalid ranges or incorrect cross references.

The attributes with problems are: rprIfProtectionSlowTimer, RprIfAtdTimer, RprIfKeepaliveTimeout, RprTopoImageStationIfIndex, and all xxxxTimeElapsed attributes.

Proposed Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

A copy of the proposed new MIB text and a "diff" against the current MIB text are separately provided.

Rationale For Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

Make sure the MIB text matches the main body clauses, and make sure that the data reported matches the MIB definitions.

Remedy's Effect On Existing Equipment [If more space is needed, provide an additional file, preferably as plain text.]

None.

When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.