

IEEE 802.17 Maintenance Request 0018

MR number 0018 Classification Technical Date received 3/13/2005 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 416 Subclause B.2.1.6.1 Figure _____ Table _____

Surname Lemon Given Name John

Perceived Problem [If more space is needed, please provide an additional file, preferably as plain text.]

802.3 MAC attributes were mistakenly added to the PacketPHY.

Proposed Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

Remove the 802.3 preamble and IPG from the PacketPHY.

Rationale For Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

See attached text.

Remedy's Effect On Existing Equipment [If more space is needed, provide an additional file, preferably as plain text.]

1G and 10G PHYs are capable of working with without these 10/100 leftovers.

When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.