

IEEE 802.17 Maintenance Request 0019

MR number 0019 Classification Technical Date received 3/13/2005 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 112 Subclause 7.5.7.2.4 Figure _____ Table 7.11

Surname Lemon Given Name John

Perceived Problem [If more space is needed, please provide an additional file, preferably as plain text.]

The classC credits are being saved before updating them.

Proposed Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

Move "lastCreditC = creditC;" from first line to last line of the action for Row 9.

Rationale For Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

The credit amount is stored for comparison in subsequent runs through the shaper in Row 5. This is done to determine if frames are being held too long. So, the credit amount needs to be saved after shaper adjustment.

Remedy's Effect On Existing Equipment [If more space is needed, provide an additional file, preferably as plain text.]

New equipment with this fixed will not impact equipment already deployed with this incorrect order of setting the saved value.

When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.