

IEEE 802.17 Maintenance Request 0024

MR number 0024 Classification Technical Date received 3/13/2005 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 112 Subclause 7.5.7.2.4 Figure _____ Table 7.11

Surname Lemon Given Name John

Perceived Problem [If more space is needed, please provide an additional file, preferably as plain text.]

Table 7.11 and Table 7.12 do not check at entry to the statemachine if the TICK time has expired.

Proposed Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

In Table 7.11, reverse the order of Row 1 and Row 2. In Table 7.12, reverse the order of Row 1 and Row 2.

Rationale For Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

The current text would always wait for no FE bytes to be available before providing new credits.

Remedy's Effect On Existing Equipment [If more space is needed, provide an additional file, preferably as plain text.]

None.

When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.