

## IEEE 802.17 Maintenance Request 0086

MR number 0086 Classification Technical Date received 10/3/2005 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 395 Subclause 12.6.1.2 Figure \_\_\_\_\_ Table \_\_\_\_\_

Surname Lemon Given Name John

**Perceived Problem** [ If more space is needed, please provide an additional file, preferably as plain text. ]

scffErrors is insufficiently defined, yielding possibly different results in different implementations.

**Proposed Remedy** [ If more space is needed, please provide an additional file, preferably as plain text. ]

Formally define scffErrors in Clause 7 by adding the variable declaration to 7.2.2 and then to 7.6.3.6.2 and then by adding the incrementing of the variable to Table 7.20 in each of the following rows: 12, 13, 20, 21, and 23.

**Rationale For Remedy** [ If more space is needed, please provide an additional file, preferably as plain text. ]

Specifying the precise cases in which the variable is incremented disambiguates the assumed conditions that lead to the final value of this variable.

**Remedy's Effect On Existing Equipment** [ If more space is needed, provide an additional file, preferably as plain text. ]

None.

**When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.**