

IEEE 802.17 Maintenance Request 0115

MR number 0115 Classification Technical Date received 7/3/2006 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 143 Subclause 7.6.3.10.2 Figure _____ Table _____

Surname Ram Given Name Rafi

Perceived Problem [If more space is needed, please provide an additional file, preferably as plain text.]

The badRxFcsFrames statistics counter is not reflected in any MIB item.

Proposed Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

Add the following MIB items :

rprSpanErrorCurrentBadRxFcsFrames
rprSpanErrorIntervalBadRxFcsFrames
rprSpanErrorDayBadRxFcsFrames
rprSpanErrorStatsBadRxFcsFrames

Rationale For Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

Minimal change, consistent with the way the badFcsFrames counter is reflected in the MIB.

Remedy's Effect On Existing Equipment [If more space is needed, provide an additional file, preferably as plain text.]

No effect.

When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.